
Meridian 1

Digital Trunk Interface/ Computer-to-PBX Interface

Description

Document Number: 553-2811-100

Document Release: Standard 4.0

Date: December 1994

© 1991, 1994

All rights reserved

Printed in the United States of America

Information is subject to change without notice. Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Revision history

September 16, 1991

Standard, release 1.0. Reissued for compliance with Northern Telecom standard 164.0.

December 1, 1991

Standard, release 2.0. This document is reissued to include technical content updates. Due to the extent of changes revision bars are omitted.

August 1, 1993

Standard, release 3.0. This document is reissued for updates and changes resulting from X11 release 19. All updates are noted with revision bars in the margins.

December 1994

Standard, release 4.0. Reissued to include technical content updates. All updates are noted with revision bars in the margins.

Contents

Introduction	1
Document overview	1
Other documentation	2
Digital Trunk Interface feature	3
Computer-to-PBX Interface application	4
Benefits	5
North American T1 carrier DS-1 frame organization	5
B8ZS line coding method	7
Extended Superframe format	7
Functions	11
Digital Trunk Interface	11
DTI software	11
Meridian 1/DS-1 conversion	12
Idle, unequipped, or disabled DS-1 channel states	12
Processing of A & B signaling bits	12
Control of pad switching	12
Meridian 1 data protocol converter	12
Echo Canceller control	13
Maintenance functions	13
Data transmission and reception	13
Controlled slips	13
Clock Controller synchronization	13
Synchronization criteria	14
Clock Control	14
Tracking supervision	15

Bit error rates	15
Frame slip	15
Frame alignment	16
Clock distribution	16
Clock switchover	17
Phase locked loop	17
Automatic clock recovery	17
Feature operation	19
Voice call processing	19
Outgoing calls	20
Incoming calls	21
Data call processing	21
Mixed voice/data	22
Voice calls only	23
Data calls only	23
Data call limitations	23
Recognition of data calls	23
Digital connectivity	24
Digital pad control	24
DTI/CPI Channel Classmarks	25
Echo Cancellor	26
Tandem switches	26
Trunk supervision	26
Computer-to-PBX Interface application	27
Public Switched Data Service	28
Operation	29
Configurations	29
Receiving data calls	30
Equipment	31
Required firmware	31
Installation-dependent hardware	31
Required hardware	32

QPC472 and QPC720 hardware description	33
Physical description	33
Faceplate LEDs	35
Transmission equalizer switch	35
Faceplate connectors	38
QPC471 and QPC775 Clock Controllers	39
Clock Controller Enable/Disable switch and indicator	40
Clock Controller switch settings	44
Clocks per system	46
Clock Controller interconnections	46
Interfacing with common carriers	47
Echo Canceller interface	47

List of figures

Figure 1	
Typical Meridian 1 to Meridian 1 communication by means of DTI	3
Figure 2	
Typical Meridian 1 to host computer communication by means of CPI	4
Figure 3	
DS-1 frame format	6
Figure 4	
Framing format	6
Figure 5	
Public Switched Data Service between Meridian 1 and Central Office	28
Figure 6	
QPC472/QPC720 faceplate jacks and LEDs	34
Figure 7	
QPC472/QPC720 DIP switch locations and settings	37
Figure 8	
XN and XT multi-group operation	41
Figure 9	
N and NT single-group operation	42
Figure 10	
N, NT, MS, ST, and RT half-group operation	43

List of tables

Table 1	
Extended Superframe format	8
Table 2	
Network signaling on DTI	22
Table 3	
DTI Channel Classmarks	25
Table 4	
QPC472 transmission equalization switch settings for DTI	36
Table 5	
QPC720 transmission equalization	
SW2 switch settings for PRI/DTI	36
Table 6	
DTI/Echo Cancellor RS-232-C interface pin assignments	38
Table 7	
DTI/QPC472 J5/QPC720 J4 Carrier Interface pinouts	39
Table 8	
QPC471 vintages A through G Clock Controller switch settings	44
Table 9	
QPC471 vintage H Clock Controller switch settings	45
Table 10	
Meridian 1 system clock requirements	46
Table 11	
DTI/Echo Cancellor interface	47

Table 12	
Command protocol	48
Table 13	
Echo Cancellor command keys	49